

| <u>Test Report</u> | | | Number: | SZHH00644141 | |
|--|---------------------------|---|-----------------------------------|--------------|--|
| Applicant: | | | Date: | Nov 18, 2011 | |
| Sample Descriptio Twenty (20) s | on: submitted sample s | said to be Bike Tire Repair Glue. SZHH00644141 | | | |
| Tests conducted: As requested by the applicant, refer to attached page(s) for details. | | | | | |
| Conclusion: <u>Tested Samples</u> <u>Standard</u> Tested components of Flash Point Test submitted samples Standard | | **** | <u>Result</u> See test conduct | | |

Authorized by: For Intertek Testing Services Shenzhen Ltd.

lug

Ben N.L. Lin General Manager



<u>Test Report</u>

Number: SZHH00644141

Tests Conducted

1 Flammability test

With reference to 16 CFR 1500.43(a) and 1500.3(c)(6) analysis.

Tested component Result

Liquid Glue: 15 °c. Flash

Remark :

| Flashpoint | Substance to be considered as | | |
|--|-------------------------------|--|--|
| At or below -6.7°c | Extremely flammable | | |
| Above -6.7°c and below 37.8°c | Flammable | | |
| At or above 37.8°c to and including 65.6°c | Combustible | | |

Result:

According to the 16 CFR 1500.3(c)(6), the liquid is considered to be an flammable.

Date sample received: Nov 11, 2011 , Nov 17, 2011 & Nov 18, 2011 Testing period: Nov 11, 2011 to Nov 18, 2011

End of report